



Devil's Slide/Hwy 1 Storm Repair

Daily Updates from Bijan Sartipi



Daily Update
June 3 and 4

Repair Work

Devil's Slide (post mile 39.14)

- Shotcreting below the road continued on Saturday.



Applying shotcrete to prevent erosion of the cliff surface.

- Construction of wall 'A' continues. Approximately 50 feet of concreting was completed Saturday.



Crews continue to build bracing wall 'A' this weekend.

- Drilling and installation of tie backs for wall 'A' continued.



Getting ready to install another 150 feet long tie back.

- Assembly of scaffolding for constructing the second bracing wall above the road started this weekend.



Assembling scaffolding for whaler wall 'D'.